



**FARMAN F121 JABIRU**  
 free flight model **SHEET**  
 by George Sneed **2**



Ribs: 1 & 2 cut from 1.6mm  
 3 to 10 cut from 1.3mm  
 11 from 3mm.  
 Lighten ribs by cutting holes with sharpened tubes. (Source: redundant radio aerials).

Les cahiers de **C.E.R.V.I.A.**



4 off